

Government of India-Ministry of Railways Research Designs & Standards Organisation Lucknow - 226 011 DID (0522) 2450115

DID (0522) 2465310



Dated: 04.05.2023 No. CT/USFD/ACS

Principal Chief Engineer Chief Administrative Officer (Cons) & All concerned (As per mailing list enclosed)

> **Sub:** Manual for ultrasonic testing of rails and welds (Revised 2022) - Addendum and Corrigendum slip no.1 of May, 2023

Ref: This office letter no. CT/USFD dated 29.04.2022

- 1. The "Manual for ultrasonic testing of rails and welds, (Revised 2022)" was circulated to all Zonal Railways vide this office letter at reference above.
- 2. Vide Agenda item no. 1.2 "Action to be taken in case of detection of DFWN" was discussed and deliberated in CTEs' Seminar held at IRICEN/Pune on 07th to 8th April-2022. Forum recommended that Board may give intervening period for removal of DFWN and the marking as being done on NCR i.e. two stars with N marked for DFWN may be approved by Railway Board for uniform adoption by all.
- 3. Further, Railway Board's order on recommendations of above CTEs' Seminar (Agenda item no. 1.2) issued vide letter no. 2022/CE-II/TK/CTES/22302 dated 19.01.2023, have been incorporated in Para 8.10.1 & Foot note of Para 8.14 of USFD Manual through ACS. Please find enclosed herewith Addendum and Corrigendum slip no. 1 of May, 2023 to the above Manual for information and further necessary action.

Enclosure: As above

ASAD MUSTAFA RIZVI

Digitally signed by ASAD MUSTAFA RIZVI Date: 2023.05.04 16:59:45 +05'30'

(Asad M. Rizvi) Executive Director/Track-I

Mailing list

I. Principal Chief Engineer

- 1. Central Railway, Mumbai CST 400001
- 2. Eastern Railway, Fairlie Place, Kolkata 700001
- 3. Northern Railway, Baroda House, New Delhi 110001
- **4.** N.E. Railway, Gorakhpur 273012
- 5. Southern Railway, Park Town, Chennai 600003
- **6.** S.C. Railway, Rail Nilayam, Secunderabad 500371
- 7. Western Railway, Churchgate, Mumbai 400020
- 8. South Eastern Railway, Garden Reach, Kolkata 700043
- 9. N.F. Railway, Maligaon, Guwahati 781011
- 10. East Central Railway, Hajipur 844101
- 11. East Coast Railway, Bhubaneshwar 364001
- 12. North Central Railway, HQ Office, Subedarganj, Block Bhagirathi, Prayagraj 211015
- 13. North Western Railway, Jaipur 755001
- 14. South East Central Railway, Bilaspur 495004
- **15.** South Western Railway, Hubli 580023
- 16. West Central Railway, Jabalpur 482001

II. Chief Administrative Officer (Cons)

- **1.** Central Railway, New Administrative Office Building, 6th Floor, D.N. Road, Mumbai CST 400001
- **2.** CAO (I), Eastern Railway, 4th Floor, New Koilaghat Building, Strand Road, Kolkata 700001
- **3.** CAO (II), Eastern Railway, 4th Floor, New Koilaghat Building, Strand Road, Kolkata 70000
- 4. Northern Railway, Kashmere Gate, Delhi 110001
- 5. USBRL Project, Opp. R.R.B. Jammu Tawi 180013
- 6. North Eastern Railway, Gorakhpur 273012
- 7. Southern Railway, Egmore, Chennai 600003
- **8.** West Central Railway, Jabalpur 482001
- 9. South Western Railway, 18, Millar Road, Bangalore 560046
- **10.** South Central Railway, Rail Nilayam, Secunderabad 500371
- 11. South Eastern Railway, Garden Reach, Kolkata 700043
- **12.** East Coast Railway, Chandrashekharpur, Bhubaneshwar 751023
- **13.** Western Railway, Churchgate 400020
- 14. CAO (North), East Central Railway, Mahendrughat, Patna 800004
- 15. CAO (South), East Central Railway, Mahendrughat, Patna 800004
- **16.** North Western Railway, Near Railway Station, Jaipur 302001
- **17.** South East Central Railway, Bilaspur 495004 (Chhattisgarh)
- 18. North Central Railway, HQ Office, Subedargani, Block Bhagirathi, Prayagraj 211015
- **19.** CAO (I), N.F. Railway, Guwahati 781001
- **20.** CAO (II), N.F. Railway, Guwahati 781001
- **21.** CAO (III), N.F. Railway, Guwahati 781001

III. PEDs/EDs of Railway Board and RDSO

- 1. Principal Executive Director/CE (P), Railway Board, Rail Bhawan, New Delhi 110001
- 2. Executive Director, Track (M & MC), Railway Board, Rail Bhawan, New Delhi 110001
- 3. Executive Director/Track-II, RDSO, Lucknow
- 4. Executive Director/M&C, RDSO, Lucknow.

IV. Chairman-cum-Managing Directors

- 1. The General Manager (Cons.), N.F. Railway, Maligaon, Guwahati-781 011.
- **2.** The Chief Commissioner of Railway Safety, Ministry of Tourism & Civil Aviation, NE Rly Compound, 16-A, Ashok Marg, Lucknow 260 001.
- 3. Metro Railways, Metro Bhawan, 33/1 Chowringhee Road, Kolkata-700071
- **4.** The CMD, Managing Director, KRCL, Belapur Bhawan, Plot No.6, CBD, Belapur, New Bombay-400 614.
- 5. The Director General, Railway Staff College, Vadodara-390 004.
- **6.** The Director, IRICEN, Pune- 411 001.
- 7. The Executive Director, IRCAMTECH, Maharajpur Gwalior-474 020

V. The Chief Safety Officer:

- 1. Central Railway, CST, Mumbai 400 001.
- **2.** Eastern Railway, Fairlie Place, Calcutta 700 001.
- **3.** East Central Railway, Hajipur 844 101.
- **4.** East Coast Railway, Chandrasekharpur, Bhubaneshwar 751 016.
- 5. Northern Railway, Baroda House, New Delhi 110 001.
- 6. North Central Railway, Allahabad 211 001.
- **7.** N.E. Railway, Gorakhpur 273 001.
- **8.** N.F. Railway, Maligaon, Guwahati 781 011.
- **9.** North Western Railway, Jaipur 302 001.
- **10.** Southern Railway, Park Town, Chennai 600 003.
- **11.** S.C.Railway, Rail Nilayam, Secunderabad 500 371.
- **12.** S.E. Railway, Garden Reach, Calcutta 700 043.
- 13. South East Central Railway, Bilaspur 495 004
- 14. South Western Railway, Hubli–580 023.
- 15. Western Railway, Churchgate, Mumbai 400 020
- **16.** West Central Railway, Jabalpur 482 001.

'MANUAL FOR ULTRASONIC TESTING OF RAILS AND WELDS, (Revised-2022)' ADDENDUM AND CORRIGENDUM SLIP No. 1 Dated 04.05.2023

1. Para 8.10.1 shall be replaced as under:

8.10.1 The defective joints (DFWN) based on the criteria mentioned in preceding paras and para 8.12.3 shall not be allowed to remain in service and shall be removed within a period of 1 month after initial USFD testing of AT welds. The protection of defective joints (DFWN) shall be ensured by joggled fish plate with two tight clamps immediately along with proper support on wooden block till its removal. During Subsequent testing within the guarantee period of contract defective joints (DFWO or DFWR) shall be cropped, re-welded and tested again. The re-welded joints shall be scanned ultrasonically again with the same set of acceptance criteria to ensure freedom from any harmful defects.

2. Foot note below the table of Para 8.14 shall be replaced as under:

Note: In case of defective joints (DFWN), two stars with N is to be marked by painting on both faces of weld in head with red paint. DFWN found in "Initial Acceptance Test" shall be removed from track as per para 8.10.1.

Digitally signed by RAJEEV PACHAURI Date: 2023.05.04 10:03:47 +05'30'

Digitally signed by Gaurav Verma
Date: 2023.05.04 09:48:36 +05'30'