# File No.RDSO-BnS0ESTR(CB-2)/7/2021-O/o ED/STRUCTURES/RDSO

आर, के, श्रीवास्तव R. K. Srivastava

### कार्यकारी निदेशक/पुल एवं संरचना Executive Director/B&S



भारत सरकार - रेल मंत्रालय अनुसंघान अभिकल्प और मानक संगठन लखनऊ - 226011

Government of India - Ministry of Railways Rosearch Designs and Standards Organisation Lucknow - 226011 Rly.: 032-42120, Phone / Fax: 0522-2450398

Email: odberdso@gmail.com

दिनांक: 31.05.2023

#### सं.: CBS/IRBM

Principal Chief Engineer, All Indian Railways and Metro Railway/Kolkata. The General Manager (Const.), N.F.Railway, Guwahati. The CAO/Const., All Indian Railways. The CAO/Const., Metro Railway, Mumbai & Chennai. PFA, All Indian Railwavs.

Addl. Member (Civil Engg.) Railway Board, Rail Bhawan, New Delhi - 110001. Addl. Member (Works) Railway Board, Rail Bhawan, New Delhi - 110001. Principal Executive Director/Bridges, Railway Board, Rail Bhawan, New Delhi -

Executive Director Civil Engg./B&S, Railway Board, Rail Bhawan, New Delhi -110001.

DLW/Varanasi. Manager (Engg.) ICF/Channai, RCF/Kapurthala, General CLW/Chittranjan, W&AP/ Yelahanka, Bengaluru & DMW/Patiala. Chief Commissioner of Railway Safety, Ashok Marg, NE Railway Compound, Lucknow, Uttar Pradesh 226001.

Managing Director, Konkan Railway Corporation Ltd, (KRCL), Post Box No:-9, Belapur Bhawan, Sector-11, CBD Belapur, Navi Mumbai - 400614, Maharashtra. Chairman & Managing Director, IRCON, C - 4, District Centre, Saket New Delhi -

Chairman & Managing Director, RITES, RITES Bhavan, Plot No - 1, Sector- 29, 100017.

Gurgaon Harayana. Chairman, DMRC, Metro Bhawan, 13, Fire Bridge Lane, Barakhamba Road New

Chairman & Managing Director, CONCOR, Concor Bhawan, C-3, Mathura Road, Opp. Appolo Hospital New Delhi - 110076.

Chairman & Managing Director, RVNL, 1st Floor, August Kranti Bhavan, Bhikaji Cama Place, R.K.Puram, New Delhi.

Chairman, DFCCIL, 5th Floor, Pragati Maidan, Metro Station Building Complex New Delhi - 110001.

Chairman & Managing Director, (MRVC), 2nd Floor, Churchgate Station Building, Churchgate, Mumbai - 400020.

Chairman, (RLDA), Near Safdarjang Rly. Station, Moti Bagh, New Delhi - 110021. Managing Director NHSRCL, Asia Bhavan, Sector - 9, Ilnd Floor, Road No. - 205, Dwarka Delhi.

Managing Director, Pipavav Rail Corporation Ltd, B 1202, B Wing, 12 th Floor, Statesman House, 148 Barakhamba Road, New Delhi -110001.

Director General, IRICEN, 11 A South Main Road, Koregaon Park, Pune 411001. Director General, IRIEEN, Post Box 233, Nasik Road - 422101, Nasik,

Director General, NAIR, Lalbaug, Vadodara - 390004, Gujarat.

Director General, IRITM, Manak Nagar, Lucknow.

Director General, IRISET, Secunderabad.

Director General, IRIMEE, Jamalpur.

#### File No.RDSO-BnS0ESTR(CB-2)/7/2021-O/o ED/STRUCTURES/RDSO

Genl. Secy., AIRF, NFIR, IRPOF, FROA, AIRPFA, DAI (Railways) Rail Bhawan, New Delhi.

> Advance Correction Slip No. 39 to Indian Railway Bridge Manual. विषय: सन्दर्भः

EDCE/B&S Railway Board's letter no. 2015/CE-

III/BR/POM/Seminar dated 10,05,2023

On above subject, Advance Correction Slip No. 39 of Indian Railway Bridge Manual regarding modification in Para 1107 (7) (h), duly approved by Railway Board vide letter under reference, is enclosed for information and necessary action please.

Receipt of this letter may please be acknowledged.

संलग्नक: As above

(राजेश कुमार श्रीवास्तव) (Rajesh Kumar Srivastava) कार्यकारी निदेशक/पुल एवं संरचना

**Executive Director/B&S** 

# File No.RDSO-BnS0ESTR(CB-2)/7/2021-O/o ED/STRUCTURES/RDSO

### भारत सरकार GOVERNMENT OF INDIA रेल मंत्रालय MINISTRY OF RAILWAYS (रेलवे बोर्ड RAILWAY BOARD)

## INDIAN RAILWAYS BRIDGE MANUAL (IRBM)

FIRST ADOPTED - 1967 FIRST REVISION - 1998

ADVANCE CORRECTION SLIP NO. 39 DATED: 31.05.2023

Existing para 1107 (7) (h) is to be modified to read as under:-

Rail Joints: It should be checked whether any rail joint is existing on girder bridges of 6.1 m span and less and on arch bridges having insufficient cushion.

Lucknow

Dated: 31.05.2023

By Order

(Rajesh Kumar Srivastava)

Executive Director (B&S)

**RDSO**